C103~ + Cus. ad

EPA Region 5 Records Ctr.
350669

217/786-6692 4500 South Sixth Street Springfield, Illinois 62706

Refer to: Taxewell County - LPC 17981802 - Washington/Weaver

November 2, 1976

Mr. Glenn Weaver c/o Weaver Trucking Service Beg 146 Weshington, Illinois 61571

Dear Mr. Weaver:

Your refuse disposal facility located northwest of Washington was inspected on October 25, 1976, by John Diefenback, representing this Agency.

Mr. Diefenback was unable to contact any person in authority at the time of the inspection.

... Inadequate final cover, possibly the result of erosion, was observed at the north end of the site. In addition to Rule 305(c) with regards to final cover, your attention is directed to Rule 318(b) which states, "The owner or operator shall take whatever remedial action is necessary to abate any gas, water or settling problems which appear during the three year period."

The Agency is considering presentation of the results of this investigation to the Pollution Control Board pursuant to the enforcement provisions of the Environmental Protection Act.

If you desire, you may report in writing, to the undersigned, any facts which you feel indicated that the above-noted results of our investigation are incorrect.

Sincerely,

Rene Van Someren, Regional Supervisor Land Field Operations Section Division of Land/Noise Pollution Control

RVS: JWD:kb/ad

co: Division File Central Region

ENVIRONMENTAL PROTECTION AGENCY

INSPECTION REPORT - SITE INVENTORY NO. / Co. - L.P.C. Date / Q3 Region # Letter Sent (Yes or No) (Responsible Party) Time: From 03:00 P Samples Taken: Yes () No 🚫 To 03:55Pm Ground Water() Surface() Other() Interviewed Cours No 1 Yes (%) No () 5 Photos Taken: Inspector LOTATE MR. WETHER Previous Inspection 4-25-76 Previous Correspondence 5-18 Site Open: Yes() No \ OPERATIONAL STATUS: TYPE OF OPERATION: **AUTHORIZATION:** Operating Sanitary Landfill (Storage () E.P.A. Permit (Salvage () Temporarily Closed () Random Dump Variance Other () A.C.D. () Closed Not Covered (x) 21(e) Closed and Covered () Quantity Received Daily(1-6) Board Order Illegal (5) SITE EVALUATION Flowing on site (X)....... Seeping (X)............ Inadequate depth over entire area (3)............... Intermediate Cover: Inadequate depth in portion(s)() or entire() required areas(1-3) Final Cover: Inadequate depth in some areas (1-3)............... Inadequate depth over entire area 60 days after area closure (4) 50 Refuse not deposited at toe of slope () Inadequate spreading and compacting () Insufficient operable equipment on site as required () (2 ea. 2-8). Operational roads unsatisfactory () Blowing litter(), dust nuisance observed(), Odor detected() (1 ea. 1-3).... Permit() Board Order Violation noted (2 ea. 2-4)........ Inadequate: Shelter() Sanitary Facilities() Emergency Communications()(1 ea.1-3) Scavenging by: Operator() Others() observed (1-3) Salvaging Observed():Improperly conducted in:Location()Operation()Storage()(1-3) General Compliance () Improvement Needed (Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.